

*Typical
Invoice*


**FRONT STREET
SHIPYARD**

Front Street Shipyard
101 Front Street
P.O. Box 558
Belfast, ME 04915
207-930-3740

Invoice: 4366
Date: 4/30/2014
Terms: Due On Receipt
Due Date: Upon Receipt
Invoice Amount: \$53,194.86

Invoice Description:
April Invoice

WC Class Yacht Company
Alvin Donald Tolosa
One Washington Street
Newport, Rhode Island 02840

Work Performed On ~~Wild Horses~~

For activity through April 30, 2014.

Work Order (#1036) Wild Horses 2013-14

Operation: 270-Electronics

02 check speedo's have not worked for some time

Labor	2.00 hrs	\$65.00/hr	\$130.00
Parts			\$2.49
Subtotal			\$132.49

Part Name	Quantity	Extension
10GA MARINE CABLE GREEN	2.0000	\$1.23
12GA MARINE CABLE GREEN	1.0000	\$0.38
WAGO TERMINAL BLOCK 3 POS	1.0000	\$0.88

Total For: 270-Electronics

Operation Subtotal	\$132.49
Sales Tax	\$0.00
Operation Total	\$132.49

Operation: 290-Mechanical

01 Mechanical Decommission

Test stove.	
Parts	\$33.67
Subtotal	\$33.67

Part Name	Quantity	Extension
BURNER CONTROL KNOB	1.0000	\$28.35
Tubular terminal 6 awg 14	2.0000	\$5.32

03 Engine removal and Install

Move engine and gen set. Uncrate engine, bolt on front frame and get ready for lift. Clean engine room, put in lighting, set genset in salon and look for a good location for seacock and strainer. Locate genset exhaust seacock, drill holes and chamfer outside edge and make spacers. Assist with engine install. Lift main engine into position. Lower engine onto beds equalize mount load, front mounts need replacing. Spec. replacement front mounts, that will carry the added weight from the house alternator, skid bracket. Lift engine remove mount bracket, have modified, clean rust out of riser, look for gasket. Machined motor mounts. Order exhaust elbow mounting gaskets and fasteners for Maurice. Install mount brackets and new mounts, align engine. Order parts for fuel manifold and look at with shaft coupling. Chase a gear output coupling retainer flange with Mack Boring. Install exhaust riser, diagnose coupling problem, research possible solutions. Epoxy coated soft patch, installed soft patch.

Labor	72.25 hrs	\$60.00/hr	\$4,335.00
Parts			\$966.70
Subtotal			\$5,301.70

Part Name	Quantity	Extension
-----------	----------	-----------